



TEXAS DEPARTMENT OF LICENSING AND REGULATION

Compliance Division/Architectural Barriers

P. O. Box 12157 • Austin, Texas 78711 • (512) 539-5669 • (877) 278-0999

Fax (512) 539-5690 • Web site: www.license.state.tx.us

REGISTERED ACCESSIBILITY SPECIALIST BULLETIN

RAS Bulletin 015

April 24, 2009

RE: Expired RAS Bulletins

The following RAS Bulletins are applicable to former RAS Procedures and revised forms, therefore, they are now expired and no longer in effect:

RAS Bulletin 004: Notices of Inspection Due (NOID)

RAS Bulletin 005: On-Line Project Registration Form

**RAS Bulletin 007: Changes to RAS Procedures – Sections II(B) & IV(A)(4);
and Project Status Update Form**

**RAS Bulletin 010: Changes to RAS Procedures – Section IV Inspections
Original Project File Required Prior to Inspection**

Compliance with current RAS Procedures (issued March 2007; effective April 1, 2007) and the use of current TDLR forms is required.

Frank S. Denton, Chair – Conroe, Texas

LuAnn Morgan – Midland, Texas

Mike Arismendez – Shallowater, Texas

Lewis Benavides – Oak Point, Texas

Fred Moses – Plano, Texas

Lilian Norman-Keeney – Taylor Lake Village, Texas

Deborah A. Yurco – Austin, Texas